

PD/250 Cnc Retrofit Quick Start Guide

MECHANICAL ASSEMBLY

Mechanical assembly instructions PD/230:

<https://www.youtube.com/watch?v=1140UK11ibY>

Mechanical assembly instructions PD/250:

<https://www.youtube.com/watch?v=Xd4HGjnid5I>

Assembly on PD/230 and PD/250 is very similar.

Some parts are better explained on one video, some other parts on the other, so please watch both.

COBRA ELECTRONIC BOARD

Please download cobra electronic board user's manual here ENG, ITA and software:

http://www.ideegeniali.it/shop/attachment.php?id_attachment=76

http://www.ideegeniali.it/shop/attachment.php?id_attachment=77

http://www.ideegeniali.it/shop/attachment.php?id_attachment=78

On page 13 or ITA manual see stepper motor wiring scheme.

Please also watch videotutorial on motor wiring:

<https://www.youtube.com/watch?v=epqAnQL48m4&t=2s>

and testing:

<https://www.youtube.com/watch?v=PWCz10r6Uko>

MACH3 SOFTWARE CONFIGURATION


Menu config / select native units



Please choose mm.

Menu config / ports and pins / motor output

Configure like this:



Then check if movement reversed:

Right arrow should move Z axis to right, left arrow to left.


If reversed, change "DirLowActive" from V to X for Z axis.

Up arrow should move tool against workpiece, Down arrow should move tool away from workpiece.

If reversed, change "DirLowActive" from V to X for X axis.

Menu config / motor tuning

Configure like this:



This dialog box works like this:

Click on button "X Axis"

Configure parameters for x axis (click on the textfields and insert numbers from keyboard):

Steps per unit: 800 (*)

Velocity mm/min: 300

Acceleration mm/sec/sec: 30

Step pulse: 0

Dir pulse : 0

Click on button "SAVE AXIS SETTINGS" (or it won't save them!)

Click on button "Z Axis"

Configure parameters for z axis:

Steps per unit: 800

Velocity mm/min: 300

Acceleration mm/sec/sec: 30

Step pulse: 0

Dir pulse : 0

Click on button "SAVE AXIS SETTINGS"

Click on button "OK"

Please note: (*) X axis is configured for mm of radius. If you prefer working with diameters instead of radius, please change 800 step per unit to 400 step per unit for X axis.